

## अंतर्राष्ट्रीय ऑटोमोटिव प्रौदयोगिकी केंद्र INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY

A Division of National Automotive Board (NAB), Govt. of India

अहस्तांतरणीय Non-Transferable

## परीक्षण रिपोर्ट **TEST REPORT**

परीक्षण रिपोर्ट संख्या/Test Report No: C T 0 G T 7 5 5 5

तिथि /Date: 27.02.2024

1.0 ग्राहक का नाम और पता:

Excellenc

ervice

NAME AND ADDRESS OF THE CUSTOMER

निर्माता का नाम और पता/NAME AND ADDRESS OF THE MANUFACTURER : M/s. Okaya Power Pvt. Limited

D8, Udyog Nagar, Rohtak Road, New Delhi-110041,India

: M/s. Sunoxx International

Vill. Panjhera, Nalagarh-Swarghat Road, Tehsil Nalagarh,

Distt. Solan(Himachal Pradesh)-174101

2.1 ग्राहक पत्र संदर्भ /CUSTOMER REFERENCE

: CCTNCLNPSMEEL169791 Dated 07-Nov-2023

3.0	DESCRIPTION OF TEST PROPERTY		
	डीयूटी का नाम /DUT Name	Battery Pack	
	बैटरी का प्रकार /Battery Type	Lead Acid	
	बैटरी क्षमता /Battery Capacity(Ah in 5 hours)	100Ah	

भाग सं. /Part -No/Model No. OPERT14012 नाम मात्र वोल्टेज / Nominal 12V Voltage मात्रा / Quantity 06 Nos ट्रेड का नाम / Trade Name **OKAYA** चित्र सं. / Drawing No. DW-1573-0 वाहन की श्रेणी/ Category E-Rickshaw of vehicle





- नमूना प्राप्त करने के तिथि /DATE OF RECEIPT OF TEST PROPERTY: 21.12.2023
- नमूना की स्थिति /CONDITION OF SAMPLE: No physical damage observed.
- परीक्षण उद्देश्य /TEST OBJECTIVE: To validate the safety requirements of battery pack as per AIS:048 as amended upto date.
- परीक्षण विधि /TEST METHOD: Test method referred from AIS:048:2009 as amended upto date .
- परीक्षण विधि से कोई विचलन या वहिष्करण /ANY DEVIATION OR EXCLUSION FROM TEST METHOD: No
- कार्यालक सत्यापन /FUNCTIONAL VERIFICATION: Functional verification done and battery pack was found satisfactory. 10.0 নিজ্জৰ্থ /CONCLUSION: The battery pack specified in Sr.No.3.0 of this test report met all the test requirements when tested as per AIS:048 as amended upto date as mentioned in Annexure-I of this report.
- 11.0 परीक्षण विवरण TEST DESCRIPTION: Please refer the Annexure-I of this report.

Prepared By	Checked & Authorized By	Approved By	*
4	3	Cheykun	Page 01 of 06
AMIT KUMAR	UDIT KAUL	SONU KR SUDRANIA	+Drw.
Senior Technical Asst.	Dy. Manager	Manager	[169791]

Office Address: Centre-I: Plot No.-26, Sector-3, HSIIDC, IMT-Manesar, Gurugram-122050. Haryana (India) Centre-II: Plot No.-01, Sector-M-11, HSIIDC, IMT-Manesar, Gurugram-122050. Haryana (India)

Phone: 0124-4586111, E-mail: team@icat.in, Website: www.icat.in

(An ISO 9001, ISO 14001 and ISO 45001 certified, Scope wise accredited as per ISO 17025 and BIS recognized agency)



परीक्षण रिपोर्ट संख्या/Test Report No: CTOGT7555

तिथि /Date 27.02.2024

- 12.0 परीक्षण की प्रदर्शन के तिथि / DATE OF PERFORMANCE OF TEST: Please refer the Annexure-I of this report.
- 13.0 परीक्षण का स्थान /LOCATION OF TEST: ICAT CENTRE-I & CENTRE-II.
- 14.0 परीक्षण अवधि/ Test Duration: 11.01.2024 to 21.02.2024
- 15.0 परीक्षण परिणाम /TEST RESULTS: Please refer the Test requirements and Results in Annexure-I of this rep

1.0	TEST REQUIREMENTS A	Annexure-I	
CI. No.	Test	Test Description	Observations/Results
2.1 EI	ectrical Tests		
2.1.1	Short Circuit test (Test ID:ICAT/ EEL /169791/01) Date of Test: 11.01.2024	Battery Pack Condition: Battery Pack fully charged (100% SOC), contained at ambient temperature.  Apply a hard short in less than one second to the battery with a conductor specified in the standard.  Test Duration: 10 minutes, or until another condition occurs which prevents completion of test (i.e. component melting, etc.)  Lab temperature: Not exceeding 30°C	Ambient temperature : 27°C  Conductor of ≤ 5mΩ was used and short was applied for 10 minutes.

Acceptance Criteria:

Prepared By	Checked & Authorized By	
1/4	Se de la constant de	REFORALIUM  DE LA COMPANIA DEL COMPANIA DEL COMPANIA DE LA COMPANIA DEL COMPANIA DEL COMPANIA DE LA COMPANIA DE LA COMPANIA DE LA COMPANIA DEL COMPAN
AMIT KUMAR	UDIT KAUL	Page 2 of 6 +Drw.
Senior Technical Asst.	Dy. Manager	[169791]

After 2 hours of observation:
At the end of the test, there shall be no:
a) Physical damage to the casing or mechanical parts.
b) Melting of components.

c) Fire or explosion.
It is acceptable for the battery to become dry at the end of the test.

202	
e-l o	f this report.
exur	e-I of this report.
0	bservations/Results
Ar 27	mbient temperature :
Co	onductor of ≤ 5mΩ was ed and short was
ap	ed and short was plied for 10 minutes.
No ex oh	physical damage, plosion or melting served.
	served.
	RI FOR AUTUM
	TO STATE OF EACH SEA
	MANESAR
	Page 2 of 6 +Drw. [169791]
-	+Drw. [169791]



परीक्षण रिपोर्ट संख्या/Test Report No: CT0GT7555

तिथि /Date 27.02.2024


2.1.2	Over Charge test (Test ID: ICAT/ EEL /169791/02) Date of Test: 08.02.2024	Battery Pack Condition: Battery Pack fully charged (100% SOC), contained at ambient temperature at 27±5°C. Duration: 10 hours The battery is to be overcharged at a constant charging current of 0.1 (C <sub>10</sub> ).  Acceptance Criteria: At the end of the test, there shall be no: a) Physical damage to the casing or other mechanical parts. b) Melting of components. c) Fire or explosion.	Battery was charged with 11A for 10 hours.  No physical damage, melting or explosion observed.  Satisfactory
-------	---	---	--

Prepared By	Checked & Authorized By	
4		MANESR MA
AMIT KUMAR	TIDET VALU	Page 3 of 6
Senior Technical Asst.	UDIT KAUL Dy. Manager	+Drw. [169791]





Prepared By	Checked & Authorized By	
100		FOR AUTOMOTIVE CONTROL OF THE PROPERTY OF THE
AMITEVIMAD		Page 4 of 6
AMIT KUMAR Senior Technical Asst.	UDIT KAUL Dy. Manager	+Drw. [169791]





परीक्षण रिपोर्ट संख्या/Test Report No: CT0GT7555

तिथि /Date 27.02.2024

2.2.2

Shock test (Test ID: ICAT/ EEL /169791/04) Date of Test: 09.02.2024



Battery Pack Condition: battery pack fully charged (100% SOC), contained at ambient temperature not exceeding 30°C, firmly held on the vibration table in vehicle mounting position. Shock test will be carried out in three-axis viz. in the vertical axis, horizontal axis and battery positioned in longitudinal direction. Acceleration: 30 g (half-sine wave) No. of shocks: 10 in each axis Duration: 15 ms of each shock Immediately after the test, discharge the battery at room temperature, at the rate of  $I = 0.2 \times Battery capacity(C_5)$ 

Acceptance Criteria:

The deterioration of battery rated capacity during discharging shall not be more than 10%. At the end of the test, there shall be no: a) Physical damage to the casing or other mechanical parts b) Fire or explosion.

Immediately after the test, Battery Pack was discharged at 20A and deterioration observed was not more than 10%.

No physical damage or explosion observed.


Satisfactory.

Prepared By	Checked & Authorized By	
4	Se la constant de la	EFOR AUTOMO
AMIT KUMAR	UDIT KAUL	Page 5 of 6 +Drw.
Senior Technical Asst.	Dy. Manager	[169791]


Prepared By	Checked & Authorized By	
4	Sign of the same o	TANKS 8 P
AMIT KUMAR	UDIT KAUL	Page 5 of 6 +Drw.
Senior Technical Asst.	Dy. Manager	[169791]



Prepared By	Checked & Authorized By	
4		EFOR AUTOMOTIVE PROPERTY OF THE PROPERTY OF TH
AMIT KUMAR	UDIT KAUL	Page 7 of 7 +Drw.
Senior Technical Asst.	Dy. Manager	[169791]




IARK	REV.NO.	DESCRIPTION	REVISED BY	DATE
Α	_			



NOTE:-CONTAINER MATERIAL: POLYPROPYLENE 1.TYPE OF BATTERY: LEAD ACID BATTERY -TUBULAR 2.NOMINAL VOLTAGE: 12 3.CAPACITY (Ah): 125Ah@C20 CORRECTED AT 30°C 4.TERMINAL POLARITY: RIGHT 5.SUITABLE APPLICATION: ELECTRIC VEHICLE







DESIGN DRAWN		CHE	CKED	APPROVED	DATE	SCALE	PART MATL./MATL.CODE	DESCRIPTION		WEIGHT		
NARINDER	SANDEE	P RA	JESH	M.SHETTY	29-02-24	1:1		SEE	NOTE		OKAYA POWER LTD	
UNSPECIFIED TOLE UNDER 4 OVER 4 UNDER 16		±0.15 ±0.2	UNS	UNSPECIFIED DRAFT ANGLE 15'~30' UNSPECIFIED RADIUS 0.2		SPECIFICATION .NO. SP.MS1832-		REVISION 00	$\oplus \Box$	D-7, UDYOG NAGAR, ROHTAK ROAD NEW DELHI		
OVER 63 UNDER 250 :		±0.3 ±0.5 ±0.8	IF IN	ALL DIMENSIONS ARE IN mm  IF IN DOUBT PLEASE ASK  DO NOT SCALE THE DRG.			PART NAME. FINISHED BATTERY FOR			DRG.NO. SHE DW-1573-A 01		SHEET 01 OF 01