

अंतर्राष्ट्रीय ऑटोमोटिव प्रौद्योगिकी केंद्र INTERNATIONAL CENTRE FOR AUTOMOTIVE TECHNOLOGY

A Division of National Automotive Board (NAB), Govt. of India

अहस्तांतरणीय Non-Transferable

परीक्षण रिपोर्ट **TEST REPORT**

परीक्षण रिपोर्ट संख्या/Test Report No: CT0GT7556

तिथि /Date: 27.02.2024

1.0 ग्राहक का नाम और पता:

Excellenc

ervice

- : M/s. Okaya Power Pvt. Limited
- NAME AND ADDRESS OF THE CUSTOMER 2.0 निर्माता का नाम और पता /NAME AND
- D8, Udyog Nagar, Rohtak Road, New Delhi-110041,India
- **ADDRESS OF THE MANUFACTURER**
- : M/s. Sunoxx International Vill. Panjhera, Nalagarh-Swarghat Road, Tehsil Nalagarh,
- Distt. Solan(Himachal Pradesh)-174101
- 2.1 ग्राहक पत्र संदर्भ /CUSTOMER REFERENCE
- : CCTNCLNPSMEEL171349 Dated 07-Nov-2023

डीयूटी का नाम /DUT Name	Battery Pack	
बैटरी का प्रकार /Battery Type	Lead Acid	12-1
बैटरी क्षमता /Battery Capacity(C5)	108Ah @ C5	11 E
भाग सं./Part -No /Model No.	OPERT15012	E20
नाम मात्र वोल्टेज / Nominal Voltage	12V	10 10 10
गात्रा / Quantity	06 Nos	
ट्रेड का नाम / Trade Name	OKAYA	
चित्र सं. / Drawing No.	DW-1581-0	
वाहन की श्रेणी/ Category of vehicle	E-Rickshaw	





- 4.0 नमूना प्राप्त करने के तिथि /DATE OF RECEIPT OF TEST PROPERTY: 21.12.2023
- 5.0 नमूना की स्थिति /CONDITION OF SAMPLE: No physical damage observed.
- परीक्षण उद्देश्य /TEST OBJECTIVE: To validate the safety requirements of traction Battery pack as per AIS:048 as amended
- 7.0 परीक्षण विधि /TEST METHOD: Test method referred from AIS:048:2009 as amended upto date .
- परीक्षण विधि से कोई विचलन या वहिष्करण /ANY DEVIATION OR EXCLUSION FROM TEST METHOD: No
- 9.0 कार्यालक सत्यापन /FUNCTIONAL VERIFICATION: Functional verification done and Battery pack was found satisfactory.
- 10.0 নিজ্ফর্য /CONCLUSION: The Battery pack specified in Sr.No.3.0 of this test report met all the test requirements when tested as per AIS:048 as amended upto date as mentioned in Annexure-I of this report.
- 11.0 परीक्षण विवरण TEST DESCRIPTION: Please refer the Annexure-I of this report.
- 12.0 परीक्षण की प्रदर्शन के तिथि / DATE OF PERFORMANCE OF TEST: Please refer the Annexure-I of this report.

Prepared By	Checked & Authorized By	Approved By	*
4	Service of the servic	Col Englerin	OR AUTOMORPHICA TO A STATE OF THE STATE OF T
AMIT KUMAR	UDIT KAUL	SONU KR SUDRANIA	Page 01 of 06 +Drw.
Senior Technical Asst.	Dy. Manager	Manager	[171349]


Office Address: Centre-I: Plot No.-26, Sector-3, HSIIDC, IMT-Manesar, Gurugram-122050. Haryana (India) Centre-II: Plot No.-01, Sector-M-11, HSIIDC, IMT-Manesar, Gurugram-122050. Haryana (India) Phone: 0124-4586111, E-mail: team@icat.in, Website: www.icat.in

(An ISO 9001, ISO 14001 and ISO 45001 certified, Scope wise accredited as per ISO 17025 and BIS recognized agency)



परीक्षण रिपोर्ट संख्या /Test Report No: CT0GT7556

तिथि /Date 27.02.2024





परीक्षण रिपोर्ट संख्या/Test Report No: CT0GT7556

तिथि /Date 27.02.2024

2.1.2	Over Charge test (Test ID: ICAT/ EEL /171349/02) Date of Test: 08.02.2024	Battery Pack Condition: Battery Pack fully charged (100% SOC), contained at ambient temperature at $27\pm5^{\circ}$ C. Duration: 10 hours The battery is to be overcharged at a constant charging current of 0.1 (C ₁₀). Acceptance Criteria: At the end of the test, there shall be no: a) Physical damage to the casing or other mechanical parts. b) Melting of components. c) Fire or explosion.	Battery was charged with 12A for 10 hours. No physical damage, melting or explosion observed. Satisfactory
-------	---	--	--


Prepared By	Checked & Authorized By	
1		TOR AUTOR
		Page 3 of 6
AMIT KUMAR	UDIT KAUL	+Drw.
Senior Technical Asst.	Dy. Manager	[171349]





2.2	Mechanical Tests							
2.2.1	Vibration test (Test ID: ICAT/ EEL /171349/06) Date of test: 21.02.2024	Battery Pack Condition: Battery pack fully charged (100% SOC), contained at ambient temperature, firmly held on the vibration table in vehicle mounting position. Vibration test will be carried out in three-axis viz. in the vertical axis, horizontal axis and battery positioned in longitudinal direction. Acceleration: 3 g (sinusoidal vibration) Frequency: 30-150 Hz Sweep rate: 1 octave per minute Duration: 2 hours in each axis Immediately after the test, discharge the battery at room temperature not exceeding 30°C, at the rate of I = 0.2 x Battery capacity(C ₅) Acceptance Criteria: During test, there shall be no electrolyte loss. The deterioration of battery rated capacity during discharging shall not be more than 10%. At the end of the test, there shall be no: a) Physical damage to the casing or other mechanical parts b) Fire or explosion	No electrolyte loss observed during test. Immediately after the test, Battery Pack was discharged at 21.6A and deterioration observed was not more than 10%. No physical damage or explosion observed. Satisfactory					

Prepared By	Checked & Authorized By	
4		MANESAR 4
AMIT KUMAR	UDIT KAUL	Page 4 of 6 +Drw.
Senior Technical Asst.	Dy. Manager	[171349]






2.2

Prepared By	Checked & Authorized By	
4	W S	THE FOR AUTOMOTIVE FO
AMIT KUMAR	UDITERATI	Page 5 of 6
Senior Technical Asst.	UDIT KAUL Dy. Manager	+Drw. [171349]


				ICA	
रीक्षण रिपो	र्ट संख्या/Test Report No: (CT0GT75	5 5 6 तिथि /Date 27.02 .	Innovation • Service • 6	
.2.2	Shock test (Test ID: ICAT/ EEL /171349/04) Date of Test: 09.02.2024	charged temperate the vibrat Shock test the vertice positioned Accelerate No. of shock test the vertice positioned Accelerate No. of shock test the commediate at room test to the determined of the determined at the end and	Pack Condition: Battery pack fully (100% SOC), contained at ambient ure not exceeding 30°C, firmly held on ion table in vehicle mounting position. It will be carried out in three-axis viz. in cal axis, horizontal axis and battery din longitudinal direction. It ion: 30 g (half-sine wave) locks: 10 in each axis 15 ms of each shock ely after the test, discharge the battery emperature, at the rate of Battery capacity(C ₅) Ince Criteria: Tororation of battery rated capacity during long shall not be more than 10%. It is don't be test, there shall be no: call damage to the casing or other all parts explosion.	Immediately after the test, Battery Pack was discharged at 21.6A and deterioration observed was not more than 10%. No physical damage or explosion observed. Satisfactory.	
	Prepared By		Checked & Authorized By		
	1		38	MANES ST. 2	



Prepared By	Checked & Authorized By	
4		MANESAR *
AMIT KUMAR	UDIT KAUL	Page 7 of 7 +Drw.
Senior Technical Asst.	Dy. Manager	[171349]



MARK	REV.NO.	DESCRIPTION	REVISED BY DATE	
Α				



NOTE:-

CONTAINER MATERIAL : POLYPROPYLENE

1.TYPE OF BATTERY: LEAD ACID BATTERY -TUBULAR

2.NOMINAL VOLTAGE:12


3.CAPACITY (Ah): 135Ah@C20 CORRECTED AT 30°C

4.TERMINAL POLARITY : RIGHT

5.SUITABLE APPLICATION: ELECTRIC VEHICLE







DESIGN D	DRAWN	CHECK	KED	APPROVED	DATE	SCALE	PART MATL./MATL.CODE	DES	CRIPTION	WEIGHT		
NARINDER SA	ANDEEP	RAJE	ESH	M.SHETTY	29-02-24	1:1		SEE	NOTE		OKAYA PO	WER LTD
UNSPECIFIED UNDER 4 OVER 4 UNDER	±0	0.15	UNSF	PECIFIED RA	DIUS 0.2		SPECIFICATION .NO. SP.MS1840-		REVISION 00	$\oplus \Box$	D-7, UDYOG NAGAR, NEW DELI	
OVER 16 UNDER OVER 63 UNDER OVER 250 ANGLE	R 250 ±0		IF IN	DIMENSIONS DOUBT PLE NOT SCALE		n	PART NAME. FINISHED B OPERT 15			DRG.NO.	-1581—A	SHEET 01 OF 01